Approved For Release 2003/10/16: CIA-RDP82M005912000200100031-6

DIRECTOR OF CENTRAL INTELLIGENCE Security Committee

SECOM-D-170

8 April 1980

	MEMORANDUM FOR:	Chief, Headquarters Engineering Branch, RECD/OL	4
	ATTENTION:		
STATINTL	FROM:	Executive Secretary	20 to 10 to
	SUBJECT:	Air Flow -	STATINT
	verbally to you blown out of th be cleaned or t	emorandum is to restate the observation made r office on 7 April 1980 about the dirt being e ceiling air ducts and our request that they hat adequate filters be installed.	
STATINTL	2. Background: Room and comprise an office combination occupied by the Community Security Group in the spring of 1978 as temporary quarters. As an inner suite there are 8 air ducts and one return vent. They were dirty when we moved in two years ago and they have not been cleaned since.		STATINTI
	During the summer months of 1978 and 1979 we were discomforted by lack of air flow. Complaints to your office resulted in tests that apparently satisfied your office although there was no change in volume or increased force of air. We were told that the vent that feeds this area was "stuck" and could not be opened wider.		
	There	was a continuous stream of soot in the form black particles that had to be cleaned up on desks and table tops.	

Hyes became irritated and throats sore.

Approved For Release 2003/10/16: CIA-RDP82M00594R000200100031-6

3. Current Situation: On Friday, 4 April 1980, the air flow came on with a much greater force than witnessed at any time in the past two years. The suite of offices was treated to a veritable soot storm. When it had not abated by late Monday, 7 April, I went to your office

I found your observations interesting. You mentioned that the people next door (recently reoccupied) had observed the poor air flow and arrangements had been made to turn the flow back on. Obviously the vent that had been "stuck" for two years in the 12-C components of the air system was unstuck. The subsequent wind storm was responsible for disturbing the accumulation of dirt that had built up over the years and our soot problem was the inevitable consequence.

I appreciated your observation that it was obvious that the dirt we now work in resulted from dirty ducts and vents. I agree with you that they are visibly dirty and would estimate that the return air vent is at least 30% blocked with a visible accummulation of dust and dirt.

I acknowledge that the solution to our problem is not an engineering one and rests in the hands of the building manager. And while I appreciate your offer to take corrective measures within your control, I do not believe that the solution rests in turning off the air so that the soot won't blow.

To cut off the air flow might solve the soot problem but it compels us to face another summer in an interior office without adequate (inspite of the tests results this is a very uncomfortable office in the summer) ventilation.

Your statement was interesting that the obvious solution, i.e., cleaning the vents and ducts, has little chance of success because of lack of response by responsible people to your previous requests. However, I petition you to again seek redress of GSA who apparently has the charge of keeping the building clean.

In that connection I would like to relate the results STATINTL of my call to the Building Managers Office which you suggested may be a proper approach. I called and spoke to a

STAŢINTL

Approved For Release 2003/10/16: CIA-RDP82M00591R000200100031-6

He listened to the problem	
and said that his clearances had not yet come through, and	
that he would need an escort to come to the office since	
he could not yet come into the building. I agreed to	
escort him for a first hand look at the problem but he	
elected to first discuss the matter with others in his	
office who would not be available until 8 April. He indicated	
that he might consult with you sounded	STATINTL
reasonable and I'm sure he will follow through. Would you	
be kind enough to provide him the benefits of your obser-	
vations in support of our claim that conditions in this	
office are less than desirable. Would you also encourage	
him to support whatever action is necessary to get corrective	
cleaning done.	

As a final step, I will write and attach a copy of this memorandum to the Agency Health and Safety Officer, providing them a sample of the soot for possible analysis and consideration as a potential health hazard.

Perhaps if we all work together, Building Engineers, Building Managers, Health and Safety officers and occupants we can arrive at a solution before we all disappear under a mound of dirt.

STATINTL

STATINTL cc:		
	ibution: g - Addressee 1 -	

STATINTL SECOM/ (4/9/80)

1 - SECOM Chrono